

Brief of Incident (Continued)

NYC911A133
File No. 5014 04/29/1991 CHURCHVILLE, NY Aircraft Reg No. N148UA Time (Local): 12:00 EDT

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: CRUISE

Findings

1. (C) TURBINE ASSEMBLY,AIR SEAL - FAILURE,PARTIAL
2. 1 ENGINE

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this incident as follows.
A FAILURE OF THE SIXTH ROTATING AIRSEAL WHICH LED TO AN UNCONTAINED ENGINE FAILURE.